



# CASE STUDY

## Combined Linen Services - Torquay

Client:	<b>Combined Linen Services</b>
Location:	<b>Torquay, Devon</b>
Commencement:	<b>December 2001</b>
Length of contract:	<b>16-20 weeks</b>
Project type:	<b>Laundry</b>

### Overview

The overall project was managed by Adrian Clay who worked closely with Kannegiesser (machinery manufacturer) from the building design phase to ensure the installation went smoothly, there was a mix of new & used equipment installed with Clay & Abbott being responsible for the design of the services & utility delivery systems and the overall equipment installation.

This project required special attention from our design team as the location of the installation was in a valley required the installation of a self supporting chimney



1



2



# CASE STUDY

## Combined Linen Services - Torquay



3



4

- 1: water tank & chimney
- 2: Internal of main laundry
- 3: Flu connections to chimney
- 4: Process pumps & pipework
- 5: Boiler steam header
- 6: finished parallel pipework



5



6